

PRODUCT CHANGE NOTIFICATION: PCN250109

January 16, 2025

Hello, Valued Roll-Rite® Customer


Change Overview:

This communication is a notice of a change to Roll-Rite fasteners that are used to attach the 30°, 45° offsets & 90° elbows. Effective December 25th, 2024, Roll-Rite will begin the process of changing the fastener that is used in all the arm offsets and 90° bow elbows. The updated fastener will require a T30 Torx bit whereas the older fastener requires an Allen wrench or Allen bit. Proper torque for the updated T30 drive fastener must be 68-75in lb. (7.6-8.4Nm)

Reason for change:

These changes overall improve the design and requirements, while resulting in a reliable, stronger and more durable system for today’s market requirements, while keeping Roll-Rite’s focus of Driving Safety Forward. The new component design is completely reverse compatible or interchangeable with the previous design.

Please review the images below of the updated design.



Items effected by change:

Name	Description
76800	Casting, Aluminum Corner - 90 Degree with Fasteners and Tether
76900	Casting, Aluminum 30 Flat Elbow
76910	Casting, 45 Flat Elbow (Each)
76915	Casting, Extreme Duty 45 Elbow for Pivot Tube



**Roll-Rite®
Manufacturing
Headquarters**
850 Industrial Drive
Gladwin, MI 48624
+1-800-297-9905

**Pulltarps®
Manufacturing
Headquarters**
1404 N. Marshall Ave
El Cajon, 92020
+1-619-432-3480

**Vango™
Manufacturing
Headquarters**
10 Plum Street
Verona, PA 15147
+1-800-443-TARP


Service Center
9700 East 104th Ave,
Unit A
Henderson, CO 80640
+1-303-288-6390

Service Center
7720 Bluff Point Dr
Houston, TX 77086
+1-281-925-3787

Service Center
5401 Louisville St NE,
Unit 2
Louisville, OH 44641
+1-234-203-2260

Service Center
323 Technology Park Dr
Torrington, CT 06790
+1-860-496-0883

Updated Service Kits For 90° corners and 30° & 45° offset elbows (bow tube)



When ordering replacement fasteners for 90° corners and 30° & 45° offset elbows (bow tube), use service kit **108913**.

Name	Description
108913	Barrel Bolt Service Kit for Standard 90°, 30° & 45° Bow Tubes



**Roll-Rite®
Manufacturing
Headquarters**
850 Industrial Drive
Gladwin, MI 48624
+1-800-297-9905

**Pulltarps®
Manufacturing
Headquarters**
1404 N. Marshall Ave
El Cajon, 92020
+1-619-432-3480

**Vango™
Manufacturing
Headquarters**
10 Plum Street
Verona, PA 15147
+1-800-443-TARP

Service Center
9700 East 104th Ave,
Unit A
Henderson, CO 80640
+1-303-288-6390

Service Center
7720 Bluff Point Dr
Houston, TX 77086
+1-281-925-3787


Service Center
5401 Louisville St NE,
Unit 2
Louisville, OH 44641
+1-234-203-2260

Service Center
323 Technology Park Dr
Torrington, CT 06790
+1-860-496-0883

ATTENTION:

Installation of Barrel Bolts

Tool Required: (2) T30 Wrenches


T30 Torx Drive

Torque Barrel Bolts to: 68-75 in-lb. (7.6- 8.4 Nm)

WARNING

This Safety Tether Must Be Installed As Shown. Failure To Do So Could Result In Severe Injury Or Death




WARNING

This Safety Tether Must Be Installed As Shown. Failure To Do So Could Result In Severe Injury Or Death



Updated Service Kits For Extreme Duty 45° offset elbows



When ordering replacement fasteners for Extreme Duty 45° offset elbows, use service kit **108914**.

Name	Description
108914	Barrel Bolt Service Kit for Extreme Duty 45° Pivot Tubes



Roll-Rite®
Manufacturing
Headquarters
 850 Industrial Drive
 Gladwin, MI 48624
 +1-800-297-9905

Pulltarps®
Manufacturing
Headquarters
 1404 N. Marshall Ave
 El Cajon, 92020
 +1-619-432-3480




Vango™
Manufacturing
Headquarters
 10 Plum Street
 Verona, PA 15147
 +1-800-443-TARP

Service Center
 9700 East 104th Ave,
 Unit A
 Henderson, CO 80640
 +1-303-288-6390

Service Center
 7720 Bluff Point Dr
 Houston, TX 77086
 +1-281-925-3787

Service Center
 5401 Louisville St NE,
 Unit 2
 Louisville, OH 44641
 +1-234-203-2260

Service Center
 323 Technology Park Dr
 Torrington, CT 06790
 +1-860-496-0883

<p>ATTENTION:</p> <p>Installation of Barrel Bolts</p> <p>Tool Required: (2) T30 Wrenches</p> <div style="text-align: center;">  <p style="color: red; font-size: small;">T30 Torx Drive</p> </div> <p>Torque Barrel Bolts to: 68-75 in-lb. (7.6- 8.4 Nm)</p>	<p>WARNING</p>	<p>WARNING</p>
	<p>This Safety Tether Must Be Installed As Shown. Failure To Do So Could Result In Severe Injury Or Death</p> 	<p>This Safety Tether Must Be Installed As Shown. Failure To Do So Could Result In Severe Injury Or Death</p> 

Response: No response to this notification is required. Requests for additional information should be directed to your Roll-Rite/Safe Fleet Regional Sales Manager or our Inside Sales Representatives by calling 800-297-9905.

Sincerely,

Jeremy C. Tennant
Product Manager



**Roll-Rite®
Manufacturing
Headquarters**
850 Industrial Drive
Gladwin, MI 48624
+1-800-297-9905

**Pulltarps®
Manufacturing
Headquarters**
1404 N. Marshall Ave
El Cajon, 92020
+1-619-432-3480

**Vango™
Manufacturing
Headquarters**
10 Plum Street
Verona, PA 15147
+1-800-443-TARP

Service Center
9700 East 104th Ave,
Unit A
Henderson, CO 80640
+1-303-288-6390

Service Center
7720 Bluff Point Dr
Houston, TX 77086
+1-281-925-3787

Service Center
5401 Louisville St NE,
Unit 2
Louisville, OH 44641
+1-234-203-2260

Service Center
323 Technology Park Dr
Torrington, CT 06790
+1-860-496-0883